

Release Note for Vigor2925 Series

| | |
|-------------------|------------------|
| Firmware Version: | 3.8.7 |
| Release Type: | Normal |
| Applied Models: | Vigor2925 Series |

Vigor2925 series is a broadband router which integrates IP layer QoS, NAT session/bandwidth management to help users control works well with large bandwidth. The state-of-art routing feature, VPN security, and Dual-WAN provide integrated benefits for professional users and small offices.

New Features

- Support auto-reboot function (time-based) for LTE WAN connection.

Improvement

- Improved: Add a note on CSM>>Web Content Filter Profile, CSM>>URL Content Filter Profile, CSM>>APP Enforcement Profile, and CSM>>DNS Filter to remind the user to create the firewall rule.
- Improved: Add TR-069 parameters for LTE ping keep alive (WAN>>Internet Access>>LTE).
- Corrected: An error message of “Please check port5” appeared every time when a user tried to configure VLAN group on LAN>>VLAN (Vigor2925F series only).
- Corrected: In PPTP VPN connection, remote dial-in user could not get DNS server IP from its LAN subnet.

Known Issue

- The WAN port can not work well with Alcatel I-040G device. The quick solution is to add another switch between Vigor2925 and Alcatel I-040G.

Notes

- None