

Release Note for Vigor167

Firmware Version:	5.2.5
Release Type:	Normal - Upgrade recommended when convenient
Applied Models:	Vigor167

New Features

- None.

Improvement

- Improved: Password mechanism changed to force admin to change the password from the default password.
- Improved: Add a note to notify users that the Tone Information for the VDSL35b line type cannot be entirely displayed on the Monitoring>>DSL Status page.
- Corrected: An issue with failure to show (ADSL/VDSL) SNMP information.
- Corrected: An issue with VDSL35b speed dropped to 17a after a few minutes.
- Corrected: An issue with failure to login from LAN via the hostname when WAN login was disabled for admin account.
- Corrected: An issue with failure to set Username and Password with special characters for TR-069 (System Management>>Management).

Known Issue

- None.

File and Modem Code

- "Vigor167_v5.2.5.zip" provides modem code 5.12.31.0, and 5.12.18.17.