

Release Note for Vigor2865ax Series

Firmware Version:	4.3.2.1
Release Type:	Normal
Applied Models:	Vigor2865ax / Vigor2865Vax / Vigor2865LVax

Vigor2865ax series features in VDSL2 35b Super Vectoring, Gigabit throughput, App-Based QoS, VPN Client/Server, and WiFi 6.

New Features

- None.

Improvement

- Corrected: An issue of system stability and router reboot.
- Corrected: An issue of self-signed certificate regeneration automatically of Vigor router before expiration.
- Corrected: An issue of Hardware Acceleration failed to accelerate the WAN to LAN sessions in the routing mode.

File and Modem Code

- "Vigor2865ax_v4.3.2.1_STD.zip" provides Annex A modem code 8B0F07_8B0701 and 8B2607_8B0B01, and Annex B modem code 8B2607_8B0B02 and 8B2817_8B0812.
- "Vigor2865ax_v4.3.2.1_MDM1.zip" provides Annex A modem code 8B1117_8B0701 and 8B0F07_8B0701, and Annex B modem code 8B2817_8B0812 and 8B2607_8B0B02. Recommended for Australia.
- "Vigor2865ax_v4.3.2.1_MDM2.zip" provides Annex A modem code 8D1917_8D0C11 and 8D1507_8D0901, and Annex B modem code 8D1917_8D0C12 and 8B2817_8B0812.
- "Vigor2865ax_v4.3.2.1_MDM3.zip" provides Annex A modem code 77C717_8D0C11 and 8D1507_8D0901, and Annex B modem code 77C717_8D0C12 and 8B2607_8B0B02.

Known Issue

- The wireless clients might encounter unexpected trouble (e.g., unable to use the printer on LAN) while accessing into Internet if the hardware acceleration is enabled.

To skip hardware acceleration for certain devices, the following telnet command can be used:

```
ppa -E -e 1
```

```
ppa -E -a AA:BB:CC:XX:XX:XX nat/bridge/ipsec
```